

Hansen Protection AS

Head office and warehouse:
Tykkemyr 27,
N-1597 Moss, Norway

Correspondence:
P.O.Box 218,
N-1501 Moss, Norway

Telephone:
+47 69 00 13 00

Telefax:
+47 69 00 13 01

Enterprise no:
NO 871 200 092

Banker:
SEB Account No.
9750.07.09921

E-mail:
hpro@hansenprotection.no

Instruction for inspection and service of vacuum packed immersion and abandonment suits

Inspection and service recommendations for Hansen Protection immersion and abandonment suits packed in a vacuum bag.

Regular inspection by ship crew:

Hansen Protection AS recommends that our immersion/abandonment suits are inspected by ship crew on a monthly basis. The inspection shall determine under which conditions the suits are stored, and status of vacuum packing. The inspector shall especially look for leakage in foil bag.

If crew inspector reveal any leakage in foil bag and/or any other damage to the suit, the suit have to be returned to Hansen Protection Service Station or an Approved Service Partner for inspection, possible repair and new vacuum packing; - or to be replaced if necessary.

Thorough inspection by Hansen Protection or Approved Service Partner:

Within date for next service or expiry date of the emergency light (if light is included), Hansen Protection recommends that all suits are being given a thorough inspection by Hansen Protection or Service Partner to reveal condition and quality on the basis of how the suits have been stored and taken care of on board vessel.

After inspection by Hansen Protection or Approved Service Partner the suit will be vacuum packed and labelled with a new packing date and next service date.

Moss, Norway, October 2016



Thomas Lund
Quality Manager